

PL-10B Connectorization kit

Designed for owners of an optical fibre fusion splicer not including the accessories that PROMAX splicers include.

The Connectorization **Kit PL-10** contains the most important tools and equipment to perform cost-efficient connections. An optical fibre cleaver and stripper are included as well as a visual fault locator, cleaning elements, etc. All the necessary elements to ensure getting successful results.



AF-004

Isopropyl alcohol cleaning wipes



AF-007

Fibre disposal unit



AF-008

Kevlar® scissors



AF-009

Connector cleaner



AF-010

SC/APC pre-polished connectors



AF-011

Mechanical splicer



PROLITE-IIB

Mini Visual Laser Source



LAMP

LED headlamp



SUITCASE

Transport and storage suitcase



AF-001

Optica fibre cleaver



AF-003

Optica fibre stripper

